

**Photo #1**


Front Left Corner of Fork Lift



**Photo #2**

Left rear of Fork Lift.






**Photo #3**

Left side fork damage.




**Photo #4**

Left side drivers  
compartment.



**Photo #5**

Right front of forklift.



**Photo #6**

Electrical power condensor  
stuck in tire.





**Photo #7**

Right side drivers compartment.




**Photo #8**

Right rear tire.



**Photo #9**


Right rear of fork lift.



**Photo #10**


Rear of fork lift.






**Photo #11**

Right side hydraulic filter.




**Photo #12**

Right side drivers compartment.



**Photo #13**

Front fork rails.



**Photo #14**

Left side hydraulic lines and pump.





**Photo #15**


Left side Hydraulic pump cover.



**Photo #16**


Left side drivers compartment.





**Photo #17**

Left side drivers door and lift rails.



**Photo #18**

Left side air filter and hydraulic pump.



**Photo #19**

Left side trailer with fork lift.



**Photo #20**

Right side trailer and fork lift.