



# PETERBILT OF SIOUX CITY

4135 HARBOR DRIVE  
PO BOX 386  
SIOUX CITY, IA 51111

Phone: (712) 252-4566 Fax: (712) 252 - 2466

TruckCare Roadside Assistance Call: 800-473-8372

## SERVICE INVOICE

RO111094431:01

P.O. Number

KELLY (712) 552-7536

Invoice Date

05/27/2020

## SERVICE INVOICE



Bill-To Customer: 25270

EISMA TRUCKING INC\*  
1661 410TH ST  
HAWARDEN, IA 51023

(712) 552-7536

Owner: 25270

EISMA TRUCKING INC\* #09  
925 AVE D  
HAWARDEN, IA 51023

V.I.N 1XPXD49XXDD192504

Engine Serial 79575324

Vehicle ID # 173611

2013 PETERBILT

Cust Unit # 09

389

Date In	Date In Service	Mileage	Engine Hrs	Date Out	Bill Type	Terms	Writer	Reviewer
05/26/2020	07/03/2012	88,814	24,390	05/26/2020	SR	N10TH	NICOSWERT	13071

### Sold Operations

Job#1 MPGDIAGNOSTIC

DIAGNOSE FOR REPAIR

SR

#### Condition

DIAGNOSE FOR REPAIR CHECK ENGINE LIGHT IS ON SHOWING HIGH OIL PRESSURE -CASE# 6630249 -  
SHOWS 100 LBS OF OIL PRESSURE AND DOESN'T MOVE

\*\*\*\*\* DO NOT FLASH \*\*\*\*\*

\*\*\*\*\* DO NOT FLASH \*\*\*\*\*

KELLY (712) 552-7536

#### Cause

#### Correction

13060 FOUND OIL PRESSURE SENSOR FAILED. REPLACED SENSOR. ALSO FILLED UP COOLANT FOR LOW  
COOLANT LIGHT ON.

Qty	Item	Description	Price Each	Extended					
		LABOR TO PERFORM REPAIRS		102.75					
1	111P/4921517CUM	SENSOR-PRESSURE	68.41	68.41					
1.45	111P/550022522	ANTIFREEZE ELC PRE DILUT 55 GA	7.99	11.59					
1	CPU	ENGINE COMPUTER HOOK UP	100.00	100.00					
Total Labor	102.75	Total Parts	80.00	Total Other	100.00	Prepay	\$0.00	Job#1 Total	282.75



# PETERBILT OF SIOUX CITY

4135 HARBOR DRIVE  
PO BOX 386  
SIOUX CITY, IA 51111

Phone: (712) 252-4566 Fax: (712) 252 - 2466

TruckCare Roadside Assistance Call: 800-473-8372

## SERVICE INVOICE

RO111094431:01

P.O. Number

KELLY (712) 552-7536

Invoice Date

05/27/2020

Bill-To Customer: 25270

EISMA TRUCKING INC\*  
1661 410TH ST  
HAWARDEN, IA 51023

Owner: 25270

EISMA TRUCKING INC\* #09  
925 AVE D  
HAWARDEN, IA 51023

(712) 552-7536

V.I.N 1XPXD49XXDD192504

Engine Serial 79575324

Vehicle ID # 173611

2013 PETERBILT

Cust Unit # 09

389

Date In	Date In Service	Mileage	Engine Hrs	Date Out	Bill Type	Terms	Writer	Reviewer
05/26/2020	07/03/2012	88,814	24,390	05/26/2020	SR	N10TH	NICOSWERT	13071

Job#2 MISCREP

MISC. REPAIR

SR

### Condition

CUSTOMER STATES THAT THE SPEED SENSOR IS INOP WHEN IT'S WET OUT -CASE# 6630249 -

\*\*\*\*\* DO NOT FLASH \*\*\*\*\*

KELLY (712) 552-7536

### Cause

### Correction

13059- OHMED OUT SENSOR, IT OHMED OUT AT 2.257 K OHMS, SAME AS A NEW SENSOR, CUT ZIP TIES AND PULLED HARNESS OUT FOUND A RUBBED ALMOST BROKEN WIRE, CUT OLD HARNESS OUT AND MADE A NEW ONE INSTALLED NEW HARNESS AND TIED IT UP

Qty	Item	Description	Price Each	Extended
		LABOR TO PERFORM REPAIRS		346.61
14	111P/CT05512	TIE-CABLE 120LB, 15.25" BLK	0.58	8.12
12	111P/CT05317	TIE-CABLE 50LB 15.5" BLK	0.31	3.72
1	111C/3823256	CONNECTOR,ELC REPAIR	10.37	10.37
4	111P/2-112DSP	PRIMARY WIRE-16 GA BLUE100FT	0.21	0.84
4	111P/2-114DSP	PRIMARY WIRE-16 GA GREEN100FT	0.21	0.84
2	111P/HT91880	TUBING-HEAT SHRNK BLK 3/16 20-	0.84	1.68
4	111P/5-025DSP	WIRE-3/8"SPLIT BLK CNVLTD POLY	0.33	1.32
1	111P/06133MMM	TAPE-ELECTRICAL SCOTCH33+ VNLP	4.98	4.98
Total Labor		346.61	Total Parts	31.87
			Total Other	0.00
			Prepay	\$0.00
			Job#2 Total	378.48

Job#3 MPRPLKINGPINS

REPLACE KING PINS HAVE LUG NUTS RE-TORQUE AFTER 50 MILES

SR

### Condition

CUSTOMER STATES THE PUSHER AXLE KING PINS NEED TO BE REPLACED - CASE# 6630249 -

KELLY (712) 552-7536

### Cause

### Correction

13059- TOOK APART DRIVERS SIDE CLEANED DRIVER SIDE AND INSTALLED NEW SEAL IN HUB ON LEFT SIDE  
13091- TOOK APART PASSENGER SIDE, CLEANED AS NEEDED, INSTALL NEW WHEEL SEAL

Qty	Item	Description	Price Each	Extended
-----	------	-------------	------------	----------

Total Labor

Total Parts

Total Other

Prepay

Job# Total



# PETERBILT OF SIOUX CITY

4135 HARBOR DRIVE  
PO BOX 386  
SIOUX CITY, IA 51111  
Phone: (712) 252-4566 Fax: (712) 252 - 2466

TruckCare Roadside Assistance Call: 800-473-8372

## SERVICE INVOICE

RO111094431:01

P.O. Number

KELLY (712) 552-7536

Invoice Date

05/27/2020

Bill-To Customer: 25270

EISMA TRUCKING INC\*  
1661 410TH ST  
HAWARDEN, IA 51023

Owner: 25270

EISMA TRUCKING INC\* #09  
925 AVE D  
HAWARDEN, IA 51023

(712) 552-7536

V.I.N 1XPXD49XXDD192504

Engine Serial 79575324  
Vehicle ID # 173611 Cust Unit # 09  
2013 PETERBILT 389

Date In	Date In Service	Mileage	Engine Hrs	Date Out	Bill Type	Terms	Writer	Reviewer
05/26/2020	07/03/2012	88,814	24,390	05/26/2020	SR	N10TH	NICOSWERT	13071

Job#4 MISCREP

MISC. REPAIR

SR

Condition

RIGHT SIDE TAG AXLE BRAKE GETS HUNG UP, CAN'T SPIN BY HAND -CASE# 6630249 -

KELLY (712) 552-7536

Cause

Correction

Qty	Item	Description	Price Each	Extended
-----	------	-------------	------------	----------

Total Labor Total Parts Total Other Prepay Job# Total

Job#5 AIR LEAK

AIR LEAK

SR

Condition

CUSTOMER STATES THERE IS AN AIR LEAK WHEN ENGAGING LOCKERS -CASE# 6630249 -

CUSTOMER STATES IT'S THE BOTTOM SWITCH BUT THEY BOTH SAY FRONT AXLE

KELLY (712) 552-7536

Cause

Correction

1364: FOUND A RUBBED AIR LINE BY THE TRANSMISSION. REPAIRED THE LINE AS NEEDED.

Qty	Item	Description	Price Each	Extended
-----	------	-------------	------------	----------

LABOR TO PERFORM REPAIRS

57.54

1 1111/71552

1/4 UNIONS NTA

4.30

4.30

Total Labor 57.54 Total Parts 4.30 Total Other 0.00 Prepay \$0.00 Job#5 Total 61.84



# PETERBILT OF SIOUX CITY

4135 HARBOR DRIVE  
PO BOX 386  
SIOUX CITY, IA 51111  
Phone: (712) 252-4566 Fax: (712) 252 - 2466

TruckCare Roadside Assistance Call: 800-473-8372

## SERVICE INVOICE

RO111094431:01

P.O. Number

KELLY (712) 552-7536

Invoice Date

05/27/2020

## SERVICE INVOICE

Bill-To Customer: 25270

**EISMA TRUCKING INC\***  
1661 410TH ST  
HAWARDEN, IA 51023

(712) 552-7536

Owner: 25270

**EISMA TRUCKING INC\* #09**  
925 AVE D  
HAWARDEN, IA 51023

V.I.N **1XPXD49XXDD192504**

Engine Serial 79575324

Vehicle ID # 173611

2013 PETERBILT

Cust Unit # 09

389

Date In	Date In Service	Mileage	Engine Hrs	Date Out	Bill Type	Terms	Writer	Reviewer
05/26/2020	07/03/2012	88,814	24,390	05/26/2020	SR	N10TH	NICOSWERT	13071

Job#6 ASR

ADDITIONAL SERVICE REQUEST ASR

SR

Condition

19087 - RIGHT SIDE MUDFLAP BRACKET SPRING IS LOOSE -CASE# 6630249 -

ADVISED CUSTOMER, NO REPAIR AT THIS TIME - 5/26 - NS

Cause

Correction

Qty	Item	Description	Price Each	Extended
-----	------	-------------	------------	----------

Total Labor	Total Parts	Total Other	Prepay	Job# Total
-------------	-------------	-------------	--------	------------

Job#7 ASR

ADDITIONAL SERVICE REQUEST ASR

SR

Condition

13060 NEEDS CLUTCH ADJ. NO FREE PLAY.

Cause

Correction

13060 ADJ CLUTCH.

Qty	Item	Description	Price Each	Extended
-----	------	-------------	------------	----------

LABOR TO PERFORM REPAIRS

68.50

Total Labor	68.50	Total Parts	0.00	Total Other	0.00	Prepay	\$0.00	Job#7 Total	68.50
-------------	-------	-------------	------	-------------	------	--------	--------	-------------	-------



# PETERBILT OF SIOUX CITY

4135 HARBOR DRIVE  
PO BOX 386  
SIOUX CITY, IA 51111  
Phone: (712) 252-4566 Fax: (712) 252 - 2466

TruckCare Roadside Assistance Call: 800-473-8372

## SERVICE INVOICE

RO111094431:01

P.O. Number

KELLY (712) 552-7536

Invoice Date

05/27/2020

Bill-To Customer: 25270

**EISMA TRUCKING INC\***  
1661 410TH ST  
HAWARDEN, IA 51023

Owner: 25270

**EISMA TRUCKING INC\* #09**  
925 AVE D  
HAWARDEN, IA 51023

(712) 552-7536

V.I.N **1XPXD49XXDD192504**

Engine Serial 79575324

Vehicle ID # 173611

Cust Unit # 09

2013 PETERBILT

389

Date In	Date In Service	Mileage	Engine Hrs	Date Out	Bill Type	Terms	Writer	Reviewer
05/26/2020	07/03/2012	88,814	24,390	05/26/2020	SR	N10TH	NICOSWERT	13071

Job#8 ASR

ADDITIONAL SERVICE REQUEST ASR

SR

Condition

1364: LIFT AXLE IS WORE OUT AND CAN NOT BE CUT.

Cause

Correction

1364: REMOVED THE AXLE AND BRACKETS. MARKED AND DRILLED THE NEW BRACKETS. INSTALLED THE NEW AXLE. PLUMED THE AIR TO IT.  
13050 - INSTALLED SHOCKS ON NEW AXLE, ASSISTED WITH INSTALLING NEW AXLE, ATTACHED FENDERS, ATTACHED AND TORQUED WHEELS  
13091- WIRED UP DUMP SWITCH SOLENOID, GREASED, INSTALL NEW HUBCAPS.

Qty	Item	Description	Price Each	Extended
		LABOR TO PERFORM REPAIRS		1,096.00
1	111P/M1N10	FUSE-10 AMP(5EA=1BOX)	1.20	1.20
2	111P/MW1209BK	CAP-HUB-CHROME ALUM-FR KNOTCH	4.36	8.72
1	111P/800A0210	KIT-SHOCKS, RIDE (NOT PRE-INS	203.47	203.47
1	111I/13141	2 X 1 X 1/4 MDRL 80 GR FLAP WH	11.47	11.47
1	111M/70011FW	1in 80 GRIT FLAP WHEEL	6.11	6.11
2	111I/EMERY	EMERY CLO	1.10	2.20
1	111I/13188	3" CIRC CRIMPED WHL BRUSH SS	23.78	23.78
2	111I/EMERY	EMERY CLO	1.10	2.20
1	111P/8A000749	13.5K AUXILIARY SUSPENSION, IN	4,828.97	4,828.97
1	111P/8A000414	MOUNT-TRUCK, TALL, 11IN TO 13	218.52	218.52
1	111I/10616	1/4 MAGNUM DRILL	4.46	4.46
1	111P/471684ZYEL	BOLT-HEX M16-2.00X120 CL10.9 Z	5.62	5.62
1	111I/71522	1/2 X 1/4 MALE CONNECTOR NTA	5.04	5.04
2	111I/71516	1/4 X 1/4 MALE CONNECTOR NTA	3.41	6.82
2	111I/71519	3/8 X 1/4 MALE CONNECTOR NTA	3.41	6.82
2	111P/AP2639	ADAPTER-PIPE BRS CPLNG 1/	2.77	5.54
2	111P/3270-0810-0100	TUBING-AIRBRAKE BLACK 1/2 OD	0.81	1.62
10	111P/3270-0610-0100	TUBING-AIRBRAKE BLACK 3/8 OD	0.73	7.30
50	111P/CT05512	TIE-CABLE 120LB, 15.25" BLK	0.58	29.00
2	111P/HT91880	TUBING-HEAT SHRNK BLK 3/16 20-	0.84	1.68
1	111I/71520	3/8 X 3/8 MALE CONNECTOR NTA	3.90	3.90
1	111P/AP2665	ADAPTER-PIPE BRS CPLNG 3/	7.05	7.05
1	111P/FG4418	FITTING-CMPRSN STRCON 1/2	5.52	5.52
		AXLE SERIAL# 436857001		



## PETERBILT OF SIOUX CITY

4135 HARBOR DRIVE  
PO BOX 386

SIOUX CITY, IA 51111

Phone: (712) 252-4566 Fax: (712) 252 - 2466

TruckCare Roadside Assistance Call: 800-473-8372

### SERVICE INVOICE

RO111094431:01

P.O. Number

KELLY (712) 552-7536

Invoice Date

05/27/2020

## SERVICE INVOICE

Bill-To Customer: 25270

**EISMA TRUCKING INC\***  
1661 410TH ST  
HAWARDEN, IA 51023

(712) 552-7536

Owner: 25270

**EISMA TRUCKING INC\* #09**  
925 AVE D  
HAWARDEN, IA 51023

V.I.N **1XPXD49XXDD192504**

Engine Serial 79575324

Vehicle ID # 173611

2013 PETERBILT

Cust Unit # 09

389

Date In	Date In Service	Mileage	Engine Hrs	Date Out	Bill Type	Terms	Writer	Reviewer
05/26/2020	07/03/2012	88,814	24,390	05/26/2020	SR	N10TH	NICOSWERT	13071

### DISCLAIMER OF WARRANTIES

ANY WARRANTIES ON THE PRODUCTS SOLD HEREBY ARE THOSE MADE BY MANUFACTURER, IF ANY. THE SELLER HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES EITHER EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTY OR MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE, AND PETERBILT OF SIOUX CITY NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF SAID PRODUCTS.

WE HEREBY CERTIFY THAT THESE GOODS WERE PRODUCED IN COMPLIANCE WITH ALL APPLICABLE REQUIREMENTS OF SECTIONS 6, 7 AND 12 OF THE FAIR LABOR STANDARDS ACT OF 1938, AS AMENDED AND OF REGULATIONS AND ORDERS OF THE ADMINISTRATOR OR WAGE AND HOUR DIVISION ISSUED UNDER SECTION 14 THEREOF.

Please remit to: Sioux City Truck Sales, Inc. PO Box 386 Sioux City, IA 51102-0386

Parts :	5,513.18
Labor :	1,671.40
Sublet :	0.00
Prepay:	\$0.00
Other Charges :	\$100.00
Misc Supplies :	75.00
EPA Charge :	10.00
Sales Tax :	515.87

**Total: 7,885.45**

Customer Signature **X**